



INSPECTION REPORT

Client:

Mr Smith

Address:

975 Lincoln Road, Peterborough,
PE1 5YD

Date Of Inspection:

04/10/2018

Technician:

Mech1

Inspection Address:

Lincoln Road, Peterborough, PE1 5YD

Light Conditions:

Good

Vehicle Details:

Registration No:

EO08 GVG

Make:

AUDI

Model:

A4

VIN:

WAUZZZ8K48A022853

Engine Code:

CAGA

Year of Registration:

2008

Engine Capacity:

2.0L

Colour:

Grey

Mileage:

75000

KEY

Satisfactory for age and mileage



Unsatisfactory for age and mileage/Issue found



Not Applicable for this vehicle



Inspection Findings

Engine Compartment:

Engine Oil Level	✓	Engine Mountings	✓
Clutch Fluid Level	✓	Accelerator Linkage	✓
Coolant Level	✓	Bonnet Hinge	✓
Antifreeze Level	✓	Bonnet Catch	✓
Brake Fluid Level	✗	Coolant Leak	✓
Power Steering Level	✓	Excess Fumes	✓
Fuel Pump	✓	Cold Starting	✓
Drive Belt/Chain	✓	Engine Oil Leaks	✓
Turbo/Supercharger	✓	Body Panels	✓
Water Pump	✓	Air Con Components	✓
Radiator	✓	Hoses/Pipes	✓
Fuel Injectors	✓		

Transmission:

Drive Shaft Assemblies	✓	Casings	✓
Linkage	✓	Backlash	✓
Gaiters	✓	Cables	✓
Bearings	✓	Mountings	✓
Universal Joints	✓	Leaks	✓
Propshaft	✓	Hydraulic System	✓

Exhaust System:

Manifold	✓	Pipes	✓
Silencer	✓	Mountings	✓
Heatshield	✗	Leaks	✓

Fuel system:

Fuel Tank	✓	Breather Pipes	✓
Tank fixings	✓	Filler Cap	✓
Fuel Lines	✓	Leaks	✓

Brake system:

Master Cylinder	✓	Disks	✓
Servo	✓	Pads	✓
Felxible Hoses	✓	Hand Brake Linkage	✓
Pipes	✓	Hand Brake Operation	✓
Connections	✓	Leaks	✓
Pedal/Linkage	✓		

Electrical Control System:

Headlights	✓	Heater Fan Operation	✓
Rear Lighs	✓	Air Con Operation	✓
Indicators	✓	Window Operation	✓
Fog Lights	✓	Wipers/Washers	✓
Side Lights	✓	Sunroof Operation	✓
Brake Lights	✓	In Car Entertainment	✓
Reverse Lights	✓	Door Locking	✓
Auxiliary Lights	✓	Battery Charging System	✓
Panel Lights	✓	Starting System	✓
Illumination Light	✓	Switches/Controls	✓
Mirrors	✓	Instruments/Functions	✓
Horn	✓	Ignition Lock	✓
Cigarette Lighter	✓		

Front Suspension:

Ball Joints	✓	Steering Rack	✓
Springs	✓	Power Steering	✓
Bumb Stops	✓	Wheel Bearings/Hubs	✓
Gaiters	✓	Sub Frame	✓
Bushes	✓	Anti Roll Bars	✓
Suspension Arms	✓	Pipes/Hoses	✓

Rear Suspension:

Springs	✓	Anti Roll Bars	✓
Bump Stops	✓	Suspension Arms	✓
Pipes/Hoses	✓	Wheel Bearings/Hubs	✓
Bushes	✓	Sub Frame	✓

Exterior Body:

Panel Condition	✓	Number Plates	✓
Bumpers	✓	Door Locks	✓
Paintwork	✓	Glass	✓
Exterior Trim	✓	Sunroof	✗
Mudflaps	✗	Fuel Filler Cover	✓
Soft Top	✓		

Interior:

Seat Upholstery	✓	Door Operation	✓
Seat Belts	✓	Dash Panel	✓
Carpets	✓	Door Seals/Hinges	✓
Seat Mechanism	✓	Mirror	✓
Steering Wheel	✓	Sunroof Trim	✓
Head Linings	✓	Parcel Shelf	✓
Visors	✓	Centre Console	✓
Interior Sills	✓	Boot Area	✓
Door Trim Panels	✓		

Wheels And Tyres:

Tyre Front N/S	✗	Wheel/Rim	✓
Tyre Front O/S	✗	Spare	✓
Tyre Rear N/S	✓	Wheel Trim	✓
Tyre Rear O/S	✓		

Underbody:

Chassis/Floorpan	✓	Shields/Covers	✓
Corrossion	✓		

Road Test: (Up to 10 miles)

Engine Performance	✓	Instruments	✓
Excess Smoke	✓	Cruise Control	✓
Overheating	✓	Steering Effort	✓
Leaks	✓	Suspension	✓
Clutch Slippage	✓	Cooling Fan	✓
Gearbox	✓	4WD	✓
Brakes	✓	Warning Lights	✓

Distance Covered:

9.5 Miles

Max Speed:

75 MPH

Weather:

Good

Road Conditions:

Good

Tyres:

	Size	Manufacturer	Tread Depth
Front N/S	195/65 R15	Falken	1mm
Front O/S	195/65 R16	Falken	1mm
Rear N/S	195/65 R17	Continental	5mm
Rear O/S	195/65 R18	Continental	5mm
Spare	195/65 R19		

Items Marked Unsatisfactory



Item	Issue	Major
Brake Fluid Level	Brake fluid level low - recommend top up.	NO
Exhaust System Heatshield	Heatshield partially torn - recommend replacing.	NO
Brake Disks & Pads	Front brake disks worn and pitted, brake pads around 2mm left- recommend replacing within 5000 miles.	NO
Tyre Front N/S and O/S	Front N/S and O/S tyres both on 1mm. currently illegal - recommend immediate replacement.	YES

Please note that items listed as "YES" in the major column should be repaired as a matter of urgency to ensure road worthyness of the vehicle. Items listed as "NO" will not affect the safety of the vehicle, however repair work is still advised.

Customer Guidance

We strongly recommend that you thoroughly read this report in full before you decide to go ahead with the purchase of the vehicle.

Whilst all reasonable care has been taken to ensure our findings are accurate, it must be noted that the inspection of the vehicle is visual and external and as such Autoremedy is unable to accept liability for failure to identify defects not apparent at the time of the inspection.

The inspection covers all items listed, however, it must be noted that no dismantling or removal of parts has been carried out.

This inspection is not a guarantee against future defects with the vehicle and this report does not constitute any form of warranty.

The Autoremedy inspector cannot guarantee the authenticity of the odometer reading.

Should you have any queries or questions regards this report please feel free to contact us at;

Autoremedy

Pinnacle House, Newark Road

Peterborough, Cambs

PE1 5YD

Email: info@autoremedy.co.uk

Tel: 01733 639000

Pictures:

